Assessment View 1.







Limited Harm




Revision A



12


Revision B

Assessment View 2.



			10.5
	View not shown due to model error - no missing information		View not shown due to model error - no missing information
Existing		Revision A	
Limited Harm	View not shown due to model error - no missing information	Revision B	View not shown due to model error - no missing information

Assessment View 3.



Camera Location (34144, 13, 192566) Beaving 216' Pitch 1' Focal Length 25mm 21/06/2022 16:00

Existing



Limited Harm



Revision A



Revision B

Assessment View 4.







_imited Harm



Revision A



Revision B

Assessment View 5.







Limited Harm



Revision A



Revision B



Existina



Limited Harm




Revision A



Revision B

Assessment View 7.



View not shown due to model error - no missing information

View not shown due to model error - no missing information

Existing

View not shown due to model error - no missing information


View not shown due to model error - no missing information

Limited Harm Revision B

Character of Growth Study

Revision A

Assessment View 8.



Carmena Location [533702, 17, 192522] Bearing 222: Pitch 0' Focal Length 25mm 21/06/2022 16.0



Revision A



Revision B

Assessment View 9.



Existing



Limited Harm





Revision B

Assessment View 10.




Existing



Limited Harm



Revision A



Revision B

Assessment View 11.










Limited Harm

Character of Growth Study

Revision B

Assessment View 12.







Contract Location [532905, 20, 192900] Bearing 129' Pitch 1' Focal Length 25mm 21/06/2022 10:00

Existing

Revision A





Limited Harm

Revision B

Assessment View 13.



Existing



Control Limited Harm



Revision A



Revision B

Assessment View 14.



Existing



Limited Harm



Revision A



Revision B

Assessment View 15.



Existina



Limited Harm



Revision A



Revision B

Assessment View 16.



Existina



I imited Harm



Revision A



Revision B

Assessment View 17.



Commen Location [38477, 15, 193122] Beaving 215° Pitch 1° Focal Length 28mm 21/06/2022 16:00

Existing



Limited Harm



Revision A



Revision B

Assessment View 18.



Existing



Limited Harm



Revision A



Revision B

Assessment View 19.



Existing



Commers Location (SSA217, 14, 192918) Beaving 205* PRICE 1* Focal Length 25mins 21/05/2022 16:00

Limited Harm



Revision A



Revision B

Assessment View 20.



Existing



Revision A



Revision B

Assessment View 21.



Existing



Limited Harm




Revision A



Revision B









Revision A



Revision B

Assessment View 23.







imited Harm



Revision A



Revision B

Assessment View 24.



Existing



Limited Harm



Revision A



Revision B

Assessment View 25.



Existing



Limited Harm



Revision A



Revision B

Assessment View 26.







Revision A







Limited Harm

Assessment View 27.



Existing



Limited Harm




Revision A



Revision B

Assessment View 28.




Existina



Limited Harm



Revision A



Revision B

Assessment View 29.



Existina



Limited Harm



Revision A



Revision B

Assessment View 30.



Existing



Limited Harm



Revision A



Revision B

Assessment View 31.



Existing



Limited Harm



Revision A



Revision B

Assessment View 32.



Existina



Limited Harm




Revision A



Revision B

Assessment View 33.



Existing



Limited Harm



Revision A



Revision B

Assessment View 34.

View not shown due to model error - no m	nissing information	Vie	ew not shown due to model error - no missing information
Existing		Revision A	
View not shown due to model error - no m	nissing information	Vie	ew not shown due to model error - no missing information

Assessment View 35.









Revision B

Assessment View 36.



Existing



Limited Harm




Revision A



Revision B

Assessment View 37.







Limited Harm



Revision A



Revision B

Assessment View 38.



Existing



Limited Harm



Revision A



Revision B

Assessment View 39.



Existing



Limited Harm



Revision A



Revision B

Assessment View 40.



Existing



Limited Harm



Revision A



Revision B

Assessment View 41.



Existing



Limited Harm



Revision A



Revision B

Assessment View 42.



Existing



Limited Harm



Revision A



Revision B

Assessment View 43.







Limited Harm



Revision A



Revision B

Assessment View 44.







Limited Harm



Revision A



Revision B



Existing



Limited Harm



Revision A




Revision B

Assessment View 46.

	View not shown due to model error - no missing information	View not shown due to model error - no missing information	
Existing Limited Harm	View not shown due to model error - no missing information	View not shown due to model error - no missing information Revision B	

Assessment View 47.



View not shown due to model error - no missing information

Limited Harm

View not shown due to model error - no missing information

Character of Growth Study

Existing

Assessment View 48.







Limited Harm



Revision A



Revision B

Assessment View 49.



Existing



Limited Harm



Revision A



Revision B

Assessment View 50.



Existing





Revision A



Revision B

Limited Harm

Assessment View 51.



Existing



Limited Harm



Revision A



Revision B

Assessment View 52.



Existing



Limited Harm



Revision A



Revision B

