Assessment View 1.



Existina



Limited Harm



Revision A



Revision B

Assessment View 2.





Existing





Revision B

Limited Harm

Assessment View 3.



Existing



Limited Harm



Revision A



Revision B

Assessment View 4.



Existing



Limited Harm



Revision A



Revision B

Assessment View 5.



Existing



Limited Harm





Revision B

Assessment View 6.



Existing



Limited Harm



Revision A



Revision B

Assessment View 7.



Existing





18

Revision B

Assessment View 8.



Existing



Limited Harm





Revision B

Assessment View 9.



Existina



imited Harm



Revision A



Revision B

Assessment View 10.



Existing



Limited Harm



Revision A



Revision B

Assessment View 11.



Existing



Limited Harm



Revision A



Revision B







Camera Location (536611, 41, 192569) Beaving 86° Pitch 4° Focal Length 25mm 21/06/2022 16:00

Limited Harm



Revision A



Revision B

Assessment View 13.





Limited Harm





Revision A



Revision B



Existing



Limited Harm



Revision A



Revision B

Assessment View 15.







Limited Harm



Revision A



Revision B

Assessment View 16.









27

Limited Harm

Assessment View 17.







Limited Harm



Revision A



Revision B

Assessment View 18.



Camera Location (SDCIPT, SD, 193948) Bearing 124* Print 0* Focil Length. 25mm 21/09/2022 (8:00 Existing



Comment Location (30327), 3) 19244 | Bearing 124* Pitch 0" Food Longth 25mm 21/06/2022 16:00 CVU.CITY 2023

Limited Harm



Revision A



Revision B

Assessment View 19.



Existing



Limited Harm



Revision A



Revision B

