

Appendix 1: Site Photographs



Photo 1: View looking east along Cattlegate Road towards Warmerdam's



Photo 2: View of the front of the 'Housienda' dwelling at the north of the site



Photo 3: View of the 'Lodge' dwelling located to the west of the site



Photo 4: View of the greenhouse (unsafe to use) at the rear of the site



Photo 5: View of the greenhouse (unsafe to use) at the rear of the site



Photo 6: View of the greenhouse (unsafe to use) at the rear of the site



Photo 7: View of a derelict outbuilding at the rear of the site



Photo 8: View looking south with a cluster of cars located to the west of the site



Photo 9: View of the 'Middle Greenhouse' at the site



Photo 10: View of the 'Middle Greenhouse' at the site



Photo 11: View of the 'Middle Greenhouse' at the site



Photo 12: View of the 'Middle Greenhouse' at the site



Photo 13: View of Storage Shed at the site



Photo 14: View of Storage Shed at the site



Photo 15: View of Storage Shed at the site



Photo 16: View of a Dilapidated house at the site



Photo 17: View of a Dilapidated house at the site



Photo 18: View of a Dilapidated house at the site



Photo 19: View of 'the Stables' at the site



Photo 20: View of 'the Stables' at the site



Photo 21: View of the Green Shed at the site



Photo 22: View of small storage shed and area at the site



Photo 23: View of derelict water tank at the site



Photo 24: View of the 'Sticks' dwelling located to the west of the site



Photo 25: View of the interior of the Warmerdam's and its large retail sales area



Photo 26: View of the entrance to Crews Hill Railway Station